

**CERTIFICATE REGARDING SAFE DRINKING WATER AND
SANITARY CONDITION CERTIFICATE**

No.- 519

Date-12.04.2024

It is certificate that an inspection team headed by P. C. Jain (Assistant Engineer) District Water Tensting Laboratory Jagdalpur (C.G.) inspected *DAV M.M. P.S. School Lalaguda, Bastanar (C.G.)* on 09.04.2024 and found that *DAV M.M. P.S. School Lalaguda, Bastanar (C.G.)* has safe drinking water facilities for student an members of staff is maintaining hygienic sanitation condition in the school and the campus as per the norms prescribed by the Central/State/Union Terriry Government.

Assistant Engineer
Public Health Engg.
Ground Water Recharge Sub-Dn.
P. C. Jain

**Assistant Engineer
PHE G.W.R. Sub Dn.
Jagdalpur (C.G)**

To

DAV M.M. P.S School
Lalaguda Bastanar
District-Bastar (C.G.)